




Assembling instruction




IMPORTANT - TWO PERSONS MINIMUM!!!



x6



x4




x12




4x30 cutter

x16




M8

x4




M8x45

x4




M8x30

x2



x1



x1



M8x60

x4



M8

x4

